## race removal

We have gone over this subject before , just had my camera handy to show 1 idea I received of this site in the past . Used the stick welder and ran a bead on the race and just tapped the sides and they will fall out . I used 5/32 rod at at 90 amps . Just showing an example I would usually tap these out with a 3/8 drift punch . Great for rollers when you can't get a puller on it well .

