

## **Club Car Precedent Battery Bucket Fix**

The seat hinges on Club Car's Precedent are integrated into the battery bucket. If the seat is improperly hooked into the hinge receiver, the plastic may break, and not properly secure the seat. When this happens, the entire battery bucket needs to be replaced to repair it. I've had this happen a few times, and it's rather time consuming, and expensive to fix. I came up with a solution that has worked great, is cheap, and only takes about 20 minutes.

Parts required:

1- Club Car 102554601 Seat hinge, trimmed as shown in pic.

1- 1/4x3/4" bolt

1- 1/4x1 1/4" fender washer, grind the edges to fit.

1- 1/4" lock nut.





